

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

#### -- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.

The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.


As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

#### -- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.

## TORQUE TUBE

THE NEWS PUBLICATION FOR MEMBERS OF THE 1937-1938 BUICK CLUB



VOLUMN XVI . NUMBER 1 . SEPTEMBER/OCTOBER 1997

BUICK 1937 11938

## TORQUE TUBE

THE NEWS PUBLICATION FOR MEMBERS OF THE 1937-1938 BUICK CLUB

VOLUMN XVI

NUMBER

SEPTEMBER/OCTOBER 1997

## THE STATE OF LOCAN #651 - Editor DER

This is the first issue in our 1997-1998 publishing year. We ended our 1996-1997 year August 31 with a total of 558 paying members, an all time high! Thanks to all our members for making the Club such a success.


Incidentally, the Club's (my) telephone area code has changed from (415) to (650). So to reach me you would now dial: (650) 941-4587.

Charles Jekofsky (#524) in Washington, DC participated in a local 4th of July parade. He got to chauffeur Congressman Albert Wynn of MD. Charles has an external speaker hidden under the right front fender and hooked up to a tape recorder. He played Glenn Miller music. The Congressman said he really enjoyed himself and would tell his friends about his ride in a '38 Buick.

This photo below shows a 1938 Roadmaster with a custom body by Fernandez and Darrin of Paris, France. The photo was taken in August at the Pebble Beach Concourse d'Elegance in Monterey, CA. The car made its debut at the 1938 Paris Automobile Show.

I saw it at the 1995 Buick National Meet in Chicago. At that time it belonged to Ray Warshawski, the owner of the J.C. Whitney Co. Ray died recently and many of his antique cars were sold. The car now belongs to the Blackhawk Collection located in the San Francisco Bay Area.

New member Rod Lorente (#1298) writes: "I don't currently own one of these cars, but I would like to restore a 1938 Century coupe if I can find one in restorable condition. I currently own a 1958









Buick Century, and it is almost restored. I just have to finish the dash and detail the engine compartment. By the way, I enjoy visiting your club's web site."

This photo, of a black 1937 4-Door Trunk Back Sedan Model 41

(top), belongs to new member Kevin Mc Dermott (#1299) in Glastonbury, CT. Kevin bought it recently. According to one of it's previous owners, it was once owned by Art Garfunkle of Simon and Garfunkle fame. Buick made over 82,000 Model 41's and we have nearly 100 in the Club.

The only model owned by more members, in our Club, is the 1938 Model 41 with 128 cars.

Another new member, Michael Dragan (#1272) of Union Lake, Michigan owns this modified 37-41. Before restoration, it was a rust free car from



Roanoke, Virginia. The car was completely disassembled and taken down to bare metal. All the doors, fenders and hood were painted separately.

New glass and upholstery was installed, all the rubber was replaced,

bumpers were rechromed and all stainless was buffed out. All mechanicals were replaced or rebuilt as needed. Wire wheels and radial tires were added. The wheel centers were drilled out to fit the original hubs. The car has it's original drive train and suspension. The headlights were con-

verted to sealed beam. The car is solid and runs and drives like new!

Seems like all our new members have '37's. This light gray '37 Special Coupe belongs to Dan Hensley (#1295) in Chattanooga, TN. When he was a boy his uncle had a '37 Special



## **TORQUE TUBE**

The TORQUE TUBE is published bi-monthly for the enjoyment of the 1937-1938 Buick Club. Membership dues are \$34.00 per year US, \$35.00 per year Canada or Mexico and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the 1937-1938 Buick Club.

Please send all articles, ads subscriptions and inquires, etc. to:

The TORQUE TUBE 1005 RILMA LANE LOS ALTOS, CA 94022 USA You can reach Harry Logan by PHONE/FAX (650) 941-4587 or by E-mail: harrylogan@earthlink.net

Editor......Harry Logan, #651
Art Director......Dug Waggoner, #10

Printer Liaison......Bill Olson, #427
Printer......Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE.

coupe. Dan thought it was the best car on the engine dismantled for the third time because of

road. But his uncle sold the car without realizing how much Dan admired it. Now at the age of 48 he has almost the same car.

Dan found his car in an ad in Hemmings. The

car was located in Milwaukee, Wisconsin. He took a week off from work to get the car and drive it home. Dan says it needs some work but

has good potential

The cover of the July/August 1996 Torque Tube shows Jose Pardo's (#558) 1937 Roadmaster and AT-6 Texan Trainer W.W.II airplane. Jose lives in Cali, Colombia. He and some friends recently purchased a narrow-gauge steam locomotive!

(Jose owns 30%). He reports it is in good working order. Jose also keeps a 1937 Special 4-Door Slant Back Sedan Model 47 in Miami, Florida to use

when he visits the USA.

The September 18th issue of Old Cars Weekly featured military vehicles. They used an article called "Buick Meets the Opposition" from our May/June Torque Tube, giving credit to our Club. The story was about the visit of the local Buick

Club to the tank and armored car collection of Jacque Littlefield. He is reported to have the largest collection of military vehicles in the United States.

One of our members is having his



bad after-market valve lifters. He had new valve lifters installed when his engine was rebuilt. It made a lot of noise and damaged his cam shaft. So he bought lifters from a different vendor.

Same problem. He had the lifters analyzed by a laboratory. They found there was very little hardening compared to the originals. So now he will

use his original lifters. (ED: On my engine rebuild, I used the original lifters. I had them re-surfaced first as shown in the photo. So far I have had no problems).

Jim Rider (#903) in Troy, MI writes: "Enjoying the Torque Tube and looking forward to each issue. My '38 Century

Sedan is my fifth pre-war Buick. I have traveled coast to coast with most of them. Keep up the good work." Thanks Jim.

Butch Leonard (#1257) in Bend, OR sent this photo, below, of his two 1938 Buicks. The modified 38-46S Sport Coupe has disc brakes, power steering and is powered by a 425 nail-head engine. The 38-66C Century Convertible has 6 carburetors (6-97's) and dual exhausts.

The July, 1997 issue of The Buick Bugle had a question from Mr. Robert Herman in Penfield, NY about 1938 Buick Steering wheels. He writes: "Perhaps somebody out there can help solve a mystery about the 1938 Buicks. George H. Damman in his 'Seventy Years of Buick' stated that the steering wheel rims were now maroon plastic. This information appears under

an illustration which clearly shows a dark steering wheel rim. I have only seen 1938 Buicks with ivory steering wheels."

"The book
'The Buick-A
Complete History' shows light
or ivory steering
wheel rims in
those illustrations
which show the

steering wheel rim clearly. They make no mention of maroon steering wheel rims for 1938, but clearly do so about the 1939 models. Can someone solve this mystery?"

Yes! 1938 Specials had ivory banjo wheels like this unrestored 38-41 belonging to Ray and Cecilia Stampley (#1156). A few Specials had the 3 spoke brown hard rubber wheel.


All Big Series cars (Century, Roadmaster and Limited) had the

mahogany or dark wheel. The few original ones I have seen have all been cracked. (Notice the dark wheel on the 1945 photo of a '38 Century on the bottom of page 13). Most Big Series owners have had their wheels restored. Most prefer ivory as they believe it looks nicer and also matches the ivory gear shift knob, map light cover and glove box lock bezel.

Here's what an original 37/38 Buick coil (left) looks like compared to a modern replacement. The original coil has Delco-Remy molded into the top plastic, a brass ring around the top and

non-removable brackets. Aftermarket coils have none of these.

that the steering wheel rims were now maroon Last June, Von Hardesty (#964) and Karl plastic. This information appears under and Dorothy Anderson (#47) drove in their




1937 convertibles from Virginia to Ohio. The Anderson's were on their way to our '37-'38 Eastern Meet in Michigan and Von was visiting family in Columbus. Ohio. Von says that truck drivers found two 1937 Buick convertibles on the road at the same time


to be something of a novelty. Karl had a CB, so he monitored the CB traffic as they drove west.

Karl had some engine problems at the Meet. Afterwards, he drove to his nephews in

Grand Ledge, MI and worked on the car. He had to replace the engine bearings. After a 4 day delay, he and Dorothy arrived back home in Virginia safe and sound with a very quiet running engine.

And we've just had word that the basic structure of





Harry

These period drawing of a blue sidemounted Buick 4-Door Sedan are from a 1938 issue of The Buick Magazine. These magazines were mailed by local dealers to potential customers. It's interesting to note that the illustrator placed the License Plate on the wrong side of the car for the drawing on the back of the of the cover. I guess that's what you call "Artistic License." (pun intended)

#### Mt. HOOD, OREGON SEPTEMBER 19-21, 1997

By Harry Logan (#651)-Los Altos, CA

My wife Margo and I left the San Francisco Bay quarters. Deer and Buffalo heads adorn the walls Area on a Tuesday in our '38 Century Coupe with along with Indian blankets. And what a beauti-

Bob and Carol Hamro (#775) in their '57 Roadmaster, Near Sacramento, we joined up with Cecil and Shirley Don (#637) in their '38 Century Sedan and Carl and Judy Dahl (#868) in their '64 Riviera.

We spent Tuesday night in Redding, CA. Lars Gulliksrud's (#1013 Oslo, Norway), parents lived there in 1946 at 1054 Butte St. I had planned to photograph the house for Lars, but alas, it is no more. The whole area has been changed from residential to commercial. A large shopping center has replaced most of the old homes. 1054 Butte St. is now a medical center. Sorry, Lars.


Then while getting gas in the town of Yreka, CA., Bob Hamro met a rancher who owned some antique cars. He invited us to his ranch. He

ful view he has of the mountains and trees from his windows.

He showed us his car collection which included a 1938 Chevrolet Coupe (my first car), 1938 Plymouth, 1939 Chevrolet sedan etc. He also has a black 1937 Roadmaster Sedan that he purchased 25 years ago from an estate in New York. He drove it to California. It still has its original upholstery and dashboard. The engine has its original paint and decal.

Then we drove into Oregon and spent Wednesday night at the Riverside Inn in Grants Pass. The Inn is located on the banks of the Rogue River. From the Inn we took a jetboat ride 14 miles down river to Hellgate Canyon where we had supper at a restaurant on the river bank. What a beautiful setting.





While eating under a canopy, over a dozen deer came over to beg for food. They seemed

pretty tame, so I think they're used to humans as they probably do this every evening.

We reached our destination of Salem, Oregon Thursday Doug and Kay Nelson, our tour hosts, live there. They took us to supper

at Rockin' Rogers, a '50's style diner. Then Friday morning we drove to the the Nelson's home

on the outskirts of Salem.

We toured his showroom (top photo) where he keeps his restored cars including a 1938 Chevrolet Convertible Coupe, 1933 Plymouth Coupe and his 1938 Century Coupe. There is also a display of

old signs, literature etc. Doug has several garages filled with unrestored cars and his workshop.

He also works on cars in the large basement of his home.

This old garage (middle) once belonged to Doug's (with baseball cap) parents. When he learned that it was to be demolished, he had it moved to his property.

Butch Leonard (#1257) drove his'38 Century Convertible over from Bend, OR. Here we see some members examining his engine. (above)

Before leaving Salem, we parked our cars in front of the State Capitol Building, built in 1938.

(top of page 7) Then we headed for Troutdale to spend the night before going up to Mt. Hood.

Some members spent Friday night at the Edgefield Inn in Troutdale. It was built in 1911 as what was then called a Poor Farm. During the

Depression, over 700 people lived and worked there. It once had over 300 acres, but now mod-

> ern homes have been built on much of the land. It's now about 25 acres and features a brewery, winery, fine dining, three pubs, movie theater, artisans, gardens and special events. (illustration on page 7)

> We took the scenic highway

along the Columbia River up to Crown Point. (middle of page 7) In1915, a stone tower was built

there to celebrate the completion of the highway. This photo of the Columbia River and our Buicks was taken from the top of the tower.

We crossed over the Columbia River into the state of Washington. While trying to do three things at the

same time (paying the bridge toll, answering a CB call and steering the car), I managed to scrape the toll booth with my left front fender. It made





a big noise and put a scratch in my fender.

Timberline Lodge at the 6,000 foot level of Mt. Hood. What a climb, but taken in stride by our Buicks. The lodge was built using native stone, wrought iron and heavy handhewn beams of Douglas Fir. A giant central fireplace and chimney, built with 400 tons of stone, is 92 feet (28 meters) high and dominates the three levels of the Lodge. On the top of this chimney stands a brass weathervane which weighs 750 pounds (340 kg). President Franklin Roosevelt dedicated this beautiful building on September 28, 1937, almost exactly 60 years before our visit.

Long time member Jack Shepherd (#138)

drove down from Canada in his beautifully restored Samarra Beige1937 Century Convertible Sedan Model 60C.

Sunday morning we said our good-byes and headed for home. Some of us drove to Sisters, a small

We spent several hours there, then headed By late Saturday afternoon we reached the south to Bend where Butch Leonard lives.

He took us to see an antique car collection. The most interesting car there for me was this Raphael Green (light green) 1938 Century Convertible Sedan (bottom of page 8) with green leather interior. It was a beauty!


After a stop to see Butch's shop in downtown Bend, (top of page 9) we headed home.


We had a small turnout, only five 37/38 Buicks (bottom) of page 7) plus a '57 Roadmaster and '64 Riviera and some modern cars. But that had no

> effect on the enjoyment of this tour. It was wonderful. We had a good time and saw many interesting sights. I drove 1,800 miles (2900 km)

> > problem (windshield wipers). Not bad for a 60 year old car.











# Another Rare 191388 Semi-Automatic Convertible


By Harry Logan (#651)-Los Altos, CA

The last issue featured an article on *Ed Camille's* (#797) semi-automatic transmission Special convertible coupe Model 46C. Now here's the story of another one. These must surely be the only two in existence!

This black 1938 Special convertible coupe was sold new with the semi-automatic transmission and sidemounts. It also has a radio, de-luxe

Then the car passed to his brother (Gary's father). He modified the car by replacing the semi-automatic transmission with a standard floor shifter and the original sidemounts were removed and the fender wells filled in. He drove the car to Texas to marry Gary's mother in the late 1940's. Then both returned to California in the car.

Gary inherited it about 15 years ago. The car



heater, clock and tan Bedford Cord upholstery. According to the firewall data plate, it originally was painted No. 518 (*Titian Maroon*) with No. 443 trim (*Tan Bedford Cord*). It is owned by Gary Guglielmo in Southern California.

The car was purchased used around 1940 by Gary's uncle, a cartoonist for Warner Brothers Studios. He was drafted into the US Army during World War II and was killed in action. is now being restored by Specialty Automotive Restorations in Pomona, CA.

The parts to restore the sidemounts were found, but a semi-automatic steering column and transmission linkage are needed to bring it back to it's original condition. Does any member have any of these parts they would be willing to sell? If so, contact Jim Thedford at Specialty Automotive. Phone: (909) 865-5957. Thanks.







By Harry Logan (#651)-Los Altos, CA

This 1938 Buick Century 4-Door Sedan Model 61

was ordered by Mr. Edwin S. Matteson on April 16, 1938 from Paul Viles Buick in Grass Valley, CA (Historic Northern California Gold Rush Town).

Mr. Matteson wanted a Buick because his father had a 1927 model that was very reliable. This photo

(top of page 13) was taken May 30 1927 and shows Mr. Matteson's father with his Buick.

He wanted a Century because he was attracted by its beauty and power. He ordered the car with Botecelli Blue (#519) paint and Tan Mohair upholstery (#410).

Mr. Matteson was a cement contractor and lived at 126 S. School Street in Grass Valley. On April 21, 1938 he "paid in full" for a Century without sidemounts. The car cost \$1520.00, seat covers (installed) \$15.00 (still on the back seat), Center grille guard \$2.95, License and registration fee \$17.77, Guide fog lights (installed) \$11.00, set of chains \$9.50 and 3 % sales tax \$46.75 for a total of \$1622.97.

Mr. Matteson's son David lives in the San Fran-

about the car. The dealer, Paul Viles, personally delivered the car around 5:30 in the afternoon. Mr. Matteson was shaving, so he asked his 17 year old son David to test drive the car. So he was the first one in his family to drive the car.

In 1942, knowing that he was about to be inducted into the military, David borrowed the car and drove with his girl friend through a blinding snowstorm over the Sierra Mountains to Carson City, NV to get married. The windshield wipers could not keep up with the falling snow, so he had to stop often to clean the windshield.

The photo, at the bottom of page 13 with Mrs. David Matteson, was taken in late 1945 before sealed beams and turn signals were added. Note the "dark" steering wheel. The smaller photo, taken in Grass Valley of Ed Matteson and his granddaughter,

shows a blue Buick in the background. Mr. Mattison drove the car until about 1968 when old age forced him to give up driving. He died in 1973. The car was then sold to Chris Van Vliet, a young man who used the car while a student at San Diego State College.

Palm Desert, CA (near Palm Springs) and the car has been there ever since. I learned of the car because Chris saw our Club's Web page and sent me an e-mail message and later some photos of the car.

The dashboard has the chevron pattern instead of the more common woodgraining. The original map light cover has



CENTURY with taupe or tan letters matching the instrument cluster.

The car has a later model carburetor, not the original Stromberg AAV-2. The motor

is still original and has been serviced but never disassembled or rebuilt.

The car came with a radio and clock but no heater. The cracked mahogany steering wheel is now covered with a leather wrap. The clock's Borg electric clock tag with string and instruction card, owners manual, radio instruction booklet, upholstery cleaning booklet, department of motor vehicle receipt for license and registration, owner identification card from the dealer and owner service policy certificate are still in the glove box.

The car has the accessory Guide fog lights, a back-up light, rear center folding bumper guard and front grille guard.




It also has it's original tan mohair upholstery, and the original woodgrained window garnish moldings, green jack and lug wrench. The headlights

have been converted to sealed beams and turn signals and have been added. Note the lights on the front fenders.

This is one of the most documented and original antique car's I have ever found. It has been a pleasure researching and writing this article. I want to thank the first owner's son David Matteson and the second owner Chris Van Vliet for all their help.






The dashboard has the chevron pattern instead of the more common woodgraining. The original map light cover has CENTURY with taupe or tan letters matching the instrument cluster.



The car has a later model carburetor, not the original Stromberg AAV-2. The motor is still original and has been serviced but never rebuilt.



The car came with a radio and clock but no heater. The cracked mahogany steering wheel is now covered with a leather wrap. The clock's Borg electric clock tag with string and instruction card, owners manual, radio instruction booklet, upholstery cleaning booklet, departement of motor vehicle receipt for license and registration, owner identification card from the dealer and owner service policy certificate are still in the glove box.



The car has the accessory Guide fog lights, a back-up light and rear center folding bumper guard (see first photo on page 12) and front grille guard. It also has it's original tan mohair upholstery, and woodgrained window garnish moldings, green jack and lug wrench. The headlights have been converted to sealed beams. Note the additional lights in the fenders that were used for turn signals. This car was advertised in the last Torque Tube and now belongs to Dave Tachney (#997) in Minnesota

## GASSTATIONS

By Clint Preslan (#461) Lakewood, OH



There is much interest among old car people in looking for old gas stations and collecting their equipment. Items that were once thrown away such as old gas pumps, signs, containers are now valuable. It's all part of the nostalgia for the "Vanishing American Roadside."

This vintage gas station is in my neighborhood in Lakewood, Ohio. It's at the intersection of Detroit Avenue and West Clifton Boulevard. It was built around 1928 by the Standard Oil Company of Ohio (Sohio) and designed to

complement the Tudor-style apartments and shops across the street. The station closed its sizable repair facilities in the mid-1970's and became a self-service station. In the early 1990's Sohio was absorbed by British Petroleum and the station was boarded up. It has been for sale since then.

This 1920's station is cream-colored stucco with an orange tile roof. It's located on Lorain Avenue in the West Park area of Cleveland, Ohio. It was out of use when this photo was taken.





And here's what they looked like in their heyday. This former gas station is now a BMW repair shop in Palo Alto, CA. It's at the corner of Forest and Alma Streets. This two bay station sold Violet Ray brand gasoline and had an auto repair shop on the side and in the back. It was called Heilman's Automotive and was in business from 1929 until 1995. This photo, below, was taken in the Los Angeles, CA area in the late 1930's. According to the sign, Golden Eagle gas was selling for 15 and 17 cents a gallon while regular Eagle was 12 1/2 cents a gallon! They also sold used tires, Firestone tires, and Willard batteries. There's also a tune up shop, lubrication shop and a car wash.



## THE MUSEUM OF Automotive History



Walter Miller (#1093), a long time automotive literature collector and dealer has recently opened *The Museum of Automobile History* in downtown Syracuse, NY. The museum is an eye-catching building lined with 20 vintage automobile billboards, some advertising cars no longer made. It is the largest museum anywhere dedicated to memorabilia and art related to the automobile.

This photo, at the bottom of page 19, shows Walter dressed to drive an early automobile. His museum has an estimated ten thousand items reflecting every aspect of car history from 1770 to the 1990's. It evokes the world that the automobile left in its wake, in extensive displays of advertising, posters,

toys, models, design drawings, fine art, folk art and more.

You can wander freely and find items pertaining to your favorite cars. Or, going in the order suggested by the displays, you can take a walk through the Age of the Automobile, starting with a newspaper account of one of the first attempts at automaking in the 1770's, and on through to letters, posters and designers' drawings of the cars of the 1990's.

Keep in mind that there are no actual cars at the museum. While other collections display cars, this museum presents the entire world around the car: its humor, its tragedies, its greatest successes and its failures. It is a time machine of the auto age!





... "this museum

presents

the entire world

around the car:

its humor;

its tragedies,

its greatest successes

and its

failures.

It is a time machine

of the auto age!"

### WELCOME TO OUR FIRST -FIRST -

#### **MEMBER**

New member Antero Rasmus (#1301) lives car now has a wooden copy. (Sounds like this will be one of the first items Antero looks for in the owner of this

owner of this 1937 Special 4-Door Sedan since 1967. He believes the vehicle served in the Finnish army during the Second World War. It is in original condition and

fully operational. The frame number is 3114419 burnt wood to make steam to run the engine.

and the engine number is 43295955. Both numbers are in the correct range for 1937 Specials.

Future plans include restoration of the paint work and replacement of the worn-out and partially broken steering wheel. During the war the car was converted to run using a carbon monoxide system. This system was installed on the back of the car after the trunk lamp was removed. The lamp was lost and the



Tanus. The driver to make steam to run the engine. That is the device on the back of

ads).

The middle

photo, taken in

Finland in 1940.

shows what the

system might have looked like.

The car is a '39

That is the device on the back of the car.

The Finnish army used some

The Finnish army used some American cars during the war. This photo shows Finnish soldiers standing in front of a '38 Dodge, '37 Buick and a camouflaged '39 Chevrolet. The Buick has sidemounts, so it is not Antero's car.

ED: Thanks to Roger Tollefsrud's (#1200) wife Sadie for translating the captions to the bottom two photos.




## 1938 REAR LICENSE PLATE HOLDER & LAMP



This rear license plate holder and lamp was used on 1938 through 1941 Buicks.

If you're thinking of replacing the one on your 1938, realize that two similar looking lamp bodies were used. The one on the left has a noticeable curve and was used on: 1938-40C-44-46-46C-46S-47-60C-66C-66S-67-80C-87 as well as some 1939 to 1941 models. The trunk designs on these



body styles was more curved as can be seen on the coupe, convertible coupe, convertible sedan and steamline sport sedan.

The lamp body on the right has a straighter configuration and was used on:1938-41-48-61-68-81-81F-90 as well as some 1939 to 1942 models. The trunk design on the above mentioned styles was straighter as can be seen on the trunk back sedans.

Just remember to take note of this difference when you're thinking of buying a replacement.

### **COMPARE COMPRESSION READINGS**

The engine of my 1938 Century Sedan has just been rebuilt. As a reference for others who are rebuilding their engine, here are my compression readings:

CYLIN	DER	READING	IN	PSI
#1		115		
#2		120		
#3	************	126		
#4		126		
#5	***************************************	120		
#6	*************	125		
#7		116		
#8		113		

The 1938 Service Manual states the normal compression range is 111 to 118 psi.

## Technical Buick TIPS Build TIPS

By Harry Logan (#651) Los Altos, CA


## SIDEMOUNT COVER RUBBER BUMPERS

There are two rubber channel strips that go on each sidemount face plate and tread cover.(A)

You can buy this rubber (B) as a strip from Bob's Automoblia and cut it yourself (the less expensive way) or buy it already cut from Lynn Steele Rubber Co.

This photo, of an unrestored cover plate (C).

still has most if it's two rubber strips and round felt bumpers. The 3" long rubber channel strips are mounted at the bottom of the cover. Mine were riveted on but you could also






use any rubber to metal adhesive.


There is also a 1" diameter felt button riveted to the top of the cover plate (C middle arrow) & (D) with two more on the back side. These could easily be made.

There are two 5" rubber stripes on the back of the tread cover (E). Not on the tread cover it-

self, but on the piece that covers the back side of the sidemounted spare tire. There are no rubber strips at the ends of the metal cover over the tire tread area.








### HOW BUICK ATTACHED FRONT FENDER WELTING

## Technical TIPS By Harry Logan (#651) Los Altos, CA

Most members know that there should be The best way to install the welting is the way the

fender welting around the rear fenders. But some do not know that Buick also put fender welting along the rear of the front fenders. This welting runs from the firewall to the back of the front fender. Fender welting was not used on the front of the fender.





Buick did it back in '37 and '38. After the fender was painted, the welting was riveted to the fenders. You can see the factory rivets in this photo of the inside of the fender. Look at the inside rear of your front fender and you should also see the factory rivets or the holes the rivets were in

## GAS GAUGE TERMINALS

By Harry Logan (#651)



This rear view of a 1937 instrument cluster (also applies to 1938) shows <u>two</u> of the four gauges require electrical connections. They are the **Battery Charge Indicator** and the **Gas Gauge**. The battery charge indicator and <u>one</u> of the <u>two gas gauge terminals</u> have <u>10-32 threads</u>. The other <u>gas gauge terminal</u> has 8-32 threads.



If you look closely at the gas gauge, you'll see that one of the terminals is slightly smaller in diameter than the other. So be careful to use the right size nuts. I have seen stripped threads because someone assumed both gas gauge terminals used the same size nuts.



**QUICK FIX FOR** THAT VEXING BUICK BELL"

By Dug Waggoner (#10) El Cerrito, CA

beautiful view can be interrupted by a sound that brake rod as it passes through the bracket. The

can be down right aggravating. If you haven't experienced this sound you are lucky. It certainly wasn't what nature or Buick had intended.

For the purposes of this technical tip we've chosen the clamor that comes from the parking brake cable that hangs directly below the torque tube. This photo shows the drive line with the rear axle attached but upside down from it's normal riding position.

Driving along the quiet countryside enjoying the tom of the torque tube that supports the parking

rubber grommet that keeps the rod centered in the bracket deteriorates over time and falls off allowing the rod to bounce and bang against the torque tube creating the "Buick Bell" sound.

A quick fix can be made with a short piece of hose slit lengthwise. Open up this slit and slide the rod inside this hose. Then slide the hose into the hole in the bracket. Just make sure the fit isn't too tight for the parking



There is a small bracket welded to the bot- brake rod but tight enough for the bracket.

Ken Fraser (#1294) P.O. Box 518 San Mateo, CA 94401

Dan Hensley (#1295) 214 Thornton Ave. Chattanooge, TN 37411 37-46

Terry Daly (#1296) 804 Park Ave. Burlingame, CA 94010

Mark Jordan (#1297) 262 Byxbee St. San Francisco, CA 94132 38-41

Rod Lorente (#1298) 62 Crescent Hill Ave. Arlington, MA 02174

Kevin McDermott (#1299) 29 Russet Road Glastonbury, CT 06033 37-41

Joe Rodriguez (#1300) 2698 Pixanne Ct. San Jose, CA 95148

Antero Rasmus (#1301) Matsinmpolku 19 Kokkola, FIN-67400 Finland

\*Former members re-joining

Leanore Naphtali (#1302) 5 Quali Run Warren, NJ 07059 38-41

Dave Andreason (#1303) 1252 Hurley Dr. Pocatello, ID 83202 38-41

Richard Smith (#824)\* 7218 Brigner Road Mechanicsburg, OH 43044 38-47

Michael Edborg (#167)\* 1731 E. Salem Avenue Fresno, CA 93720

## Parts FOR SALE

#### PARTING 1937 & 1938.

The following is just a portion of the parts available. Call with your needs.

1937 PARTS:	un your needs.
Grille, no cracks	\$250
Headlight adjusting buckets and reflectors, excellent	
Master and DeLuxe heaters	
CENTURY rear end, complete	
AA-1 Carb for Special, complete	
Rear Fenders, 40-60 Series, excellent	
SPECIAL grille shell, mint condition	
SPECIAL front fenders, non-welled, exellent	
NOS Special Running board moldings	
NOS Special U-joint	1 min - 1 min
NOS Special steering knuckles	
CENTURY sidemount fenders with mounting hardware. Left	
ROADMASTER rims	
ROADMASTER axles	
ROADMASTER front suspension	
Master heater, complete	
Coupe & 2 Dr. Sedan side stainless, complete sets	
CENTURY brake & clutch pedal assembly	
Buick 8 clock hole filler	
Bumper guards	
Century radiator	
SPECIAL radiator	
Rear springs 40 & 60, good condition	\$100. pair
Radio delete plates	
SMALL & LARGE SERIES throttle linkage	\$25.
BIG SERIES rocker assemblies	\$50.
Fender lights	\$65. pair
Trunk lights, complete	
Tail lights with lenses, all series	\$50.
Wiper transmissions	\$50. pair
SPECIAL manifold	
Throttle cable	
SPECIAL transmission	5100.
SPECIAL splash pans	\$40. pair
CENTURY hood	
Headlight switch	
Radio grilles	
Wiper motors	
Trunk hold-up arms	
Sun visors	
Bumpers	
The state of the s	The second section of the second

(continued from page 25)	
Bumper arms	\$15. each
Horn button	\$25.
Steering wheel	\$50.
40 & 60 running board brackets	\$50. set
• 1938 PARTS:	
Headlight adjusting buckets and refelectors	\$100. pair
Master and DeLuxe Heaters	
SPECIAL fuel pumps, rebuilt	\$45.
SPECIAL fuel pump cores with rebuild kits	
Trunk emblem	
40 & 60 sedan trunk lid, no rust	
Breather tubes	\$10. each
Trunk hold-up arms	
734Z starter with solenoid	
Horn button	\$10
SPECIAL hood lettering	
Defroster ducts	
Wiper transmissions	
Rear license plate stand, bracket & light for sedan	
Bumper guards	
Tail lights, complete	
Assist straps with screws	
Throttle cable	
SPECIAL radiator	
Battery tray	
Generator	
SPECIAL manifold, complete	
SPECIAL hood sides & tops	
Gas tank door	
Sedan trunk weather strip, new rubber	
Grille, no cracks, minor pitting	
· · · · · · · · · · · · · · · · · · ·	
Fender lights	
Hood ornament, minor pitting	
CENTURY hood sides and tops	550. each
• 1937-1938 PARTS:	640 1
SPECIAl rims	
Coupe Opera seats, complete, excellent	\$500. pair
SPECIAL Oil Bath air cleaner	
Auxillary radio speakers	
Horn rings	
Headlight buckets	
40-60 Series radio hanger brackets	
40-60 Series trunk hinges	
LARGE SERIES air cleaner	
40-60 kingpin sets	
Starter drives	
LARGE SERIES fan belts, new	
Map light switches	\$15.

(continued from page 26)	
SMALL SERIES spark plug covers	\$40.
SPECIAL air cleaner	\$50.
Rear fender splash aprons	\$15. each
Big Series manifold ends	\$50.
16" beauty rings	\$10. each
2 Door rear ash trays	\$20. pair
Headlight bezels	\$20. each
Trunk hinges	S75. pair
SPECIAL oil pump	\$35.
Front arm rests	
40 & 60 rear vent windows, need plating	\$50. pair
Rear view mirrors	
SPECIAL rear motor mounts	
CENTURY rear motor mounts	
40 & 60 4 dr. sedan doors	\$50. each
Front vent window frames & mechanisms	
BIG SERIES fuel pump cores	
New speedometer cables	
SPECIAL timing chair, new	
Combination King bolt bushing reamer and driver, new in the box	
Dave Tacheny (#997)	
11949 Oregon Ave. N.	
Champlin MN 55316	
Champlin, MN 55316 (612) 427-3460	
(612) 427-3460	
(612) 427-3460 	
(612) 427-3460 	
(612) 427-3460  • 1937 PARTS: Battery hold down bracket	
(612) 427-3460  • 1937 PARTS: Battery hold down bracket	
• 1937 PARTS: Battery hold down bracket Starter w/solenoid	
(612) 427-3460  • 1937 PARTS: Battery hold down bracket Starter w/solenoid Rear shocks, rebuilt, pair Heater	
• 1937 PARTS:  Battery hold down bracket  Starter w/solenoid  Rear shocks, rebuilt, pair  Heater  Dash cover w/ash trays	
• 1937 PARTS:  Battery hold down bracket  Starter w/solenoid  Rear shocks, rebuilt, pair  Heater  Dash cover w/ash trays  • 1938 SPECIAL PARTS:	
• 1937 PARTS:  Battery hold down bracket  Starter w/solenoid  Rear shocks, rebuilt, pair  Heater  Dash cover w/ash trays	
• 1937 PARTS:  Battery hold down bracket  Starter w/solenoid  Rear shocks, rebuilt, pair  Heater  Dash cover w/ash trays  • 1938 SPECIAL PARTS:  Gas tank, dented  Spare plug cover	
• 1937 PARTS:  Battery hold down bracket  Starter w/solenoid  Rear shocks, rebuilt, pair  Heater  Dash cover w/ash trays  • 1938 SPECIAL PARTS:  Gas tank, dented	
• 1937 PARTS: Battery hold down bracket Starter w/solenoid Rear shocks, rebuilt, pair Heater Dash cover w/ash trays • 1938 SPECIAL PARTS: Gas tank, dented Spare plug cover Brackets under front fender, right and left Bumper brackets, pair	
• 1937 PARTS: Battery hold down bracket Starter w/solenoid Rear shocks, rebuilt, pair Heater Dash cover w/ash trays • 1938 SPECIAL PARTS: Gas tank, dented Spare plug cover Brackets under front fender, right and left Bumper brackets, pair	
• 1937 PARTS:  Battery hold down bracket  Starter w/solenoid  Rear shocks, rebuilt, pair  Heater  Dash cover w/ash trays  • 1938 SPECIAL PARTS:  Gas tank, dented  Spare plug cover  Brackets under front fender, right and left  Bumper brackets, pair  Overhead rocker assembly	
• 1937 PARTS:  Battery hold down bracket Starter w/solenoid Rear shocks, rebuilt, pair Heater Dash cover w/ash trays • 1938 SPECIAL PARTS: Gas tank, dented Spare plug cover Brackets under front fender, right and left. Bumper brackets, pair Overhead rocker assembly Headlight w/o lights or reflectors, pair	
• 1937 PARTS:  Battery hold down bracket Starter w/solenoid Rear shocks, rebuilt, pair Heater Dash cover w/ash trays  • 1938 SPECIAL PARTS: Gas tank, dented Spare plug cover Brackets under front fender, right and left Bumper brackets, pair Overhead rocker assembly Headlight w/o lights or reflectors, pair Parking lights w/o lenses, need repairing	
• 1937 PARTS:  Battery hold down bracket  Starter w/solenoid  Rear shocks, rebuilt, pair  Heater  Dash cover w/ash trays  • 1938 SPECIAL PARTS:  Gas tank, dented  Spare plug cover  Brackets under front fender, right and left  Bumper brackets, pair  Overhead rocker assembly  Headlight w/o lights or reflectors, pair  Parking lights w/o lenses, need repairing  Radiator	
• 1937 PARTS:  Battery hold down bracket Starter w/solenoid	
• 1937 PARTS:  Battery hold down bracket Starter w/solenoid	
• 1937 PARTS: Battery hold down bracket Starter w/solenoid Rear shocks, rebuilt, pair Heater Dash cover w/ash trays • 1938 SPECIAL PARTS: Gas tank, dented Spare plug cover Brackets under front fender, right and left Bumper brackets, pair Overhead rocker assembly Headlight w/o lights or reflectors, pair Parking lights w/o lenses, need repairing Radiator 16" wheels, repainted red w/silver stripping, have five Emergency brake handle assembly Brake shoes w/hardware, two	
• 1937 PARTS: Battery hold down bracket Starter w/solenoid Rear shocks, rebuilt, pair Heater Dash cover w/ash trays • 1938 SPECIAL PARTS: Gas tank, dented Spare plug cover Brackets under front fender, right and left Bumper brackets, pair Overhead rocker assembly Headlight w/o lights or reflectors, pair Parking lights w/o lenses, need repairing Radiator 16" wheels, repainted red w/silver stripping, have five Emergency brake handle assembly Brake shoes w/hardware, two Brake drum, rear	
• 1937 PARTS: Battery hold down bracket Starter w/solenoid Rear shocks, rebuilt, pair Heater Dash cover w/ash trays • 1938 SPECIAL PARTS: Gas tank, dented Spare plug cover Brackets under front fender, right and left Bumper brackets, pair Overhead rocker assembly Headlight w/o lights or reflectors, pair Parking lights w/o lenses, need repairing Radiator 16" wheels, repainted red w/silver stripping, have five Emergency brake handle assembly Brake shoes w/hardware, two	

(continued from page 27)	
Hood hold up brackets, pair	
Horn button	
Radio hole plugs, set	
Headlight switch	
Steering wheel, banjo, needs restoring	
16 Pushrods	
Rods, 6, 2 in boxes, .030	
Transmission w/shift lever	
Hood, right and left	\$25.
Hood side panels w/chrome, pair	
Splash pans, pair	
Thermostat housing	
Air filters, have two	
Under dash vent opening knob assembly	
SPECIAL Hood center, stainless missing on both ends	
• OTHER PARTS:	
Manifold #338252-3 casting number	\$15.
Manifold #1308218-1 casting number	
Battery tray	
Spotlight, needs repair, fair	
Belt line chrome, left and right, 39 1/2" long, good	
Lee Deskin (#692)	
3927 S. Parkcrest St	
Springfield, MO 65807	
(417) 881-3763	
(417) 881-3763	

## EXTRA! EXTRA! BACK ISSUES NOW AVAILABLE

THE FOLLOWING BACK ISSUES ARE AVAILABLE FOR \$4.00 EACH POSTPAID.

- 1991-1992 Volume X Numbers 1 through 9
- 1992-1993 Volume XI Numbers 1, 2, 4, 5, 6 and 7
  - 1993-1994 Volume XII Numbers 2, 4, 5 and 6
  - 1994-1995 Volume XIII Numbers 1 through 6
  - 1995-1996 Volume XIV Numbers 2 through 6
    - 1996-97 Volume XV Numbers 3 through 6

Please make your checks payable to:

The 1937-1938 Buick Club 1005 Rilma Lane Los Altos, CA. 94022 USA

## MORE *Garts*FOR SALE

#### 1937 SPECIAL SIDEMOUNT FENDERS:

Fenders restored and in primer. Covers in very good original condition.

Call for details.....\$2,000.00 pair

Gene Allen (#165) 2305 Alpine Dr. Helena, MT 59601 (406) 443-6475

## Parts WANTED

#### WANTED FOR 1937:

For 1937 CENTURY. In excellent condition only. Will pay top dollar.

- · Horn Button
- Brown Century Steering Wheel Joe Giordano (#333) 131 N. Stewart Rd. Liberty, MO 64068

### WANTED - BACK ISSUES of the TORQUE TUBE:

Copies of Volumes I, II, III, IV, and V. Rene Delhomme, Sr. (#676) 414 Maryview Farm Rd. Lafayette, LA 70507 (318) 232-4700

## Gars FOR SALE

#### 1937 FOR SALE:

'37 SPECIAL: 48 2-Door Trunk Back Sedan. I have owned the car for the past 10 years. The engine and front end were completely redone. I have the Hampton Coach upholstery and interiorwoodgraining completed, but neither is installed as it does need the paint work first. The engine has less than 500 miles on it and has hardened valve seats for unleaded fuel. Due to my marriage and moving to a new home, I can not afford to keep the old gal and want to get it a new home. If any member is interested, they can reach me by phone, FAX or e-mail at: whitea@rocketmail.com.

\$6,500.00 negotiable.

Al White (former member) 18756 West 59th Place Golden, CO 80403 Phone: (303) 278-1048 FAX: (303) 278-0434

#### 1938 FOR SALE:

'38 SPECIAL 2-Door Sedan
All original with less than 40,000 miles.
Very nice condition. Drive anywhere.
Original owners manual and other docu
ments.Moving, must sell.

\$6,000.00 or make offer

Jodi Erickson 228 N. Sycamore Ave. Rialto, CA 92376 (909) 820-2762

### Matley Woodgraining Service

13912 S.E. 241st St. Kent, Washington 98042



Shop (206) 630-2008 Res. (206) 630-8887

"The Crowning Touch To A Quality Restoration"



### J.B. Donaldson Co.

2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505

Beautifully Recast
STEERING WHEELS

Thru 1953 Call or write for brochure



RESTORATION



SERVICES

Running Board / Rocker Moldings

1934 thru 1940

SSAE for Information

BUICK RESTORATION SERVICES

P.O. BOX 442, PERRY,

MICHIGAN

48872



1927 TO

1953

#### WIRING HARNESSES

AUTHENTIC REPRODUCTION
WIRING SYSTEMS THRU 1953
HAND CRAFTED WITH THE
FINEST MATERIALS
EACH SUPPLIED WITH:
LIMITED WARRANTY
INSTALLATION INSTRUCTIONS
SCHEMATICS

ALSO OFFERING: WIRING SUPPLIES CATALOG OR INFORMATION \$5



BOX 435 WAYNE, PA. 19087



## AUTOMOBILIA (805) 434-2963

#### 1937-38 BUICK



FRONT FLO	CORMAT
1937-38 A	Il Models
Black or E	Brown
FF-378	\$195.

DOOR BOTTOM SEAL

DOOR W	EATHERSEAL-SPONG	E
	nDW-378	
	DW-80	
Clips	WC-80	\$ .75 ea.



**EXHAUST MANIFOLDS** 1937-38 Series 60-80-90 ENDS \$180. CENTER \$182. VALVE BODY \$195.

Clip TypeDW-369	\$2.25	f
TRUNK SEAL-SEDANS. 1/2' Wide;		
Ser. 80-90TW-371	\$35.50	2
Sedans. 3/4' Wide;		
Ser 40-60 TW-371S	\$37.50	'n








TRUNK	SEAL For COUR	PES. 5/8" x 1"	
	SpongeTL-	369\$2.00	ft.
	1/2'x1'x16' TL-	-1129 \$47.5	0

CLUTCH and BRAKE PEDALS Series 40-60



HOOD REST PADS, 1937-38 6-8 Per Car. 





Brown	CB-343BN	\$5.95 ea.
PEDAL FLO	OOR SEALS; All Models	
-	FS-375	\$12.50 pr.



PLASTIC DASH KNOBS DK-37(38) \$ 6.
PLASTIC DOOR HANDLE and Window
Winder RINGS .HE-37(38)\$ 6.


......CLOCK.. CG-38 .... \$28.

1938...... DGF-380......\$5./Set



1937 ONLY! ACCELERATOR PEDALS Series 40-60 Back. AP-37BK ......\$32.00 Brown......AP-37BN ......\$35.50







SHIFT	BOOT.	1937-36 Series 40 Only				
	Black		\$	9.2	5	
	Brown	n	\$	18.	50	
Series	80-90 E	Black ONLY	S	8.5	0	

CHIEF DOOT 1007 OD Carles 10 Oaks

DOOR SILLS: Trim To Fit

GLOVE BOXES; \$27. ea.




DOOR	FERRULE INSTALATION TOO	L.
\$20.	Refundable if Returned Withi	n
2	O Dave DE-TOOL	\$29



PARKING LIGHT LENS......\$18.00 ea

2-Door \$62/pr. 4Door \$93/set.






CARB. KITS:CARTER......CK-360C \$26.00 STROMBERG...... CK-37XS \$26.00

TORQUE BALL SEAL KIT. All Models

MOTOR MOUNT, FRONT, All Models ROUND PADS ...... SP-338 ... \$10. pr. MOUNT......MM-347.. \$25. ea.






VISOR "VANITY" MIRROR, VM-379 ..... \$27, ea

TBK-343 \$26.00



1937 HUB CAPS. All Ser HC-37 \$60. ea.	
WHEEL Beauty Rings. 15' or 16' \$99./Set	of 4
1937 or 38 HOOD ORNAMENT	.\$85.





Upper Outer Kit ..... \$39.50 King Pin Sets.......\$38.50 Lower Inner Bushings.....\$20.00 Tie Rod End.....\$27.00

SOME OTHER ITEMS WE STOCK: BEARINGS. DECALS, ENGINE PAINT, DECALS, SHOP MANUALS, PARTS BOOKS, BODY BOOKS and MORE. SHIPPING;10%. max.\$9. min. \$4. Prepaid. C.O.D. Add \$5.

BOB'S AUTOMOBILIA BOX 2119 ATASCADERO CA. 93423 TELEPHONE (805) 434-2963 .VISA- MASTERCARD-DISCOVER or C.O.D. CATALOG #45 \$5.00 - PHONE ORDERS - (Write For Catalog)



### Buick...Upholstery and Top Kits 1932/1955

Since 1977 .. Hampton Coach has been producing only the finest quality Interior and Top products available for GM cars. We offer complete interior Kits Seat Upholstery, Tops and related accessories as well as "era" fabric by the yard...

Inquire Toll Free

1-888-388-8726




## New for 1937-1938 BUICK

Tel 978-388-8047



New stainless side mount emblems. Includes mounting studs and nuts on back side. \$62.50 each



New stainless convertible top latches & header hooks for 40 & 60 series Coupe & Phaeton (6 peice set) \$365.00



MAPLE LEAF FABRICATION & MACHINE

13912 SE 241st, Street, Kent, WA 98042 206-630-2008

© Torque Tube 1996-1997

